



Where Automation Connects.



## **PSW-RLX-IHB**

**IH Browser**

Configuration Software

June 20, 2019

**RELEASE NOTES**

## Your Feedback Please

We always want you to feel that you made the right decision to use our products. If you have suggestions, comments, compliments or complaints about our products, documentation, or support, please write or call us.

### ProSoft Technology, Inc.

+1 (661) 716-5100

+1 (661) 716-5101 (Fax)

[www.prosoft-technology.com](http://www.prosoft-technology.com)

support@prosoft-technology.com

IH Browser Release Notes

June 20, 2019

ProSoft Technology®, is a registered copyright of ProSoft Technology, Inc. All other brand or product names are or may be trademarks of, and are used to identify products and services of, their respective owners.

In an effort to conserve paper, ProSoft Technology no longer includes printed manuals with our product shipments. User Manuals, Datasheets, Sample Ladder Files, and Configuration Files are provided at our web site: [www.prosoft-technology.com](http://www.prosoft-technology.com)

## Content Disclaimer

This documentation is not intended as a substitute for and is not to be used for determining suitability or reliability of these products for specific user applications. It is the duty of any such user or integrator to perform the appropriate and complete risk analysis, evaluation and testing of the products with respect to the relevant specific application or use thereof. Neither ProSoft Technology nor any of its affiliates or subsidiaries shall be responsible or liable for misuse of the information contained herein. Information in this document including illustrations, specifications and dimensions may contain technical inaccuracies or typographical errors. ProSoft Technology makes no warranty or representation as to its accuracy and assumes no liability for and reserves the right to correct such inaccuracies or errors at any time without notice. If you have any suggestions for improvements or amendments or have found errors in this publication, please notify us.

No part of this document may be reproduced in any form or by any means, electronic or mechanical, including photocopying, without express written permission of ProSoft Technology. All pertinent state, regional, and local safety regulations must be observed when installing and using this product. For reasons of safety and to help ensure compliance with documented system data, only the manufacturer should perform repairs to components. When devices are used for applications with technical safety requirements, the relevant instructions must be followed. Failure to use ProSoft Technology software or approved software with our hardware products may result in injury, harm, or improper operating results. Failure to observe this information can result in injury or equipment damage.

© 2019 ProSoft Technology. All Rights Reserved.

Printed documentation is available for purchase. Contact ProSoft Technology for pricing and availability.

# Contents

Your Feedback Please.....	2
Content Disclaimer.....	2
<b>1 Start Here</b>	<b>5</b>
1.1 About the IH Browser Software.....	5
1.2 Release Enhancements.....	6
<b>2 Support, Service &amp; Warranty</b>	<b>7</b>
2.1 Contacting Technical Support.....	7
2.2 Warranty Information.....	9



# 1 Start Here

This document highlights the new features, fixes, enhancements and known issues for the RadioLinx IH Browser software.

## 1.1 About the IH Browser Software

The RadioLinx IH Browser is a configuration and monitoring tool for the RadioLinx Industrial Hotspot radios. Use RadioLinx IH Browser to view your network topology, determine the best "path" between Master, Client and Repeater radios, and detect the presence of other vendors' 802.11 radios on the network.

## 1.2 Release Enhancements

Release Version	Release Date	Description
3.1.3.17	20-June-2019	<p><b>New Features</b></p> <ul style="list-style-type: none"> <li>• None</li> </ul> <p><b>Fixes &amp; Changes</b></p> <ul style="list-style-type: none"> <li>• Fixed an issue related to file writing permissions when trying to use the IH Browser to update firmware of one or more RLX2-IHx's. The utility was unable to create a temp file and the utility exited. The problem only occurred when installation was done in the default location; Program Files Windows folder.</li> </ul> <p><b>Known Issues</b></p> <ul style="list-style-type: none"> <li>• None</li> </ul>
3.1.3.16	26-April-2019	<p><b>New Features</b></p> <ul style="list-style-type: none"> <li>• Added support for logging RLX2-IHx serial output from the IH Browser. The feature timestamps log entries and will automatically add new RLX2 devices to the logging session as they are discovered on the network. Hourly log files in date named folders are produced when logging session is active.</li> </ul> <p><b>Fixes &amp; Changes</b></p> <ul style="list-style-type: none"> <li>• None</li> </ul> <p><b>Known Issues</b></p> <ul style="list-style-type: none"> <li>• None</li> </ul>
3.1.3.15	26-Aug-2018	<p><b>New Features</b></p> <ul style="list-style-type: none"> <li>• Added support for MNAT network modes and icons.</li> <li>• Fixed the sorting of columns for <i>Retries%</i>, <i>Tx (kbit/s)</i>, and <i>Rx (kbit/s)</i>.</li> <li>• Added support in <i>Update Config</i> dialog to configure new devices. Normally the <i>Name</i> and <i>IP address</i> are preserved when uploading a configuration file. A new check box added - allows the user to specify the <i>Name</i> and <i>IP Address</i> for this new unit. These values are stored the next time the dialog is opened, making it easier to sequentially configure multiple new devices.</li> </ul>

## 2 Support, Service & Warranty

### In This Chapter

Contacting Technical Support.....	7
Warranty Information .....	9

### 2.1 Contacting Technical Support

ProSoft Technology, Inc. is committed to providing the most efficient and effective support possible. Before calling, please gather the following information to assist in expediting this process:

- 1 Product Version Number
- 2 System architecture
- 3 Network details

If the issue is hardware related, we will also need information regarding:

- 1 Module configuration and associated ladder files, if any
- 2 Module operation and any unusual behavior
- 3 Configuration/Debug status information
- 4 LED patterns
- 5 Details about the serial, Ethernet or Fieldbus devices interfaced to the module, if any.

**Note:** For technical support calls within the United States, an emergency after-hours answering system allows 24-hour/7-days-a-week pager access to one of our qualified Technical and/or Application Support Engineers. Detailed contact information for all our worldwide locations is available on the following page.

Asia Pacific	Europe / Middle East / Africa
<p><b>Regional Office</b> Phone: +60.3.2247.1898 asiapc@prosoft-technology.com Languages spoken: Bahasa, Chinese, English, Japanese, Korean REGIONAL TECH SUPPORT support.ap@prosoft-technology.com</p>	<p><b>Regional Office</b> Phone: +33.(0)5.34.36.87.20 europe@prosoft-technology.com Languages spoken: French, English REGIONAL TECH SUPPORT support.emea@prosoft-technology.com</p>
<p><b>North Asia (China, Hong Kong)</b> Phone: +86.21.5187.7337 china@prosoft-technology.com Languages spoken: Chinese, English REGIONAL TECH SUPPORT support.ap@prosoft-technology.com</p>	<p><b>Middle East &amp; Africa</b> Phone: +971.4.214.6911 mea@prosoft-technology.com Languages spoken: Hindi, English REGIONAL TECH SUPPORT support.emea@prosoft-technology.com</p>
<p><b>Southwest Asia (India, Pakistan)</b> Phone: +91.98.1063.7873 india@prosoft-technology.com Languages spoken: English, Hindi, Urdu</p>	<p><b>North Western Europe (UK, IE, IS, DK, NO, SE)</b> Phone: +44.(0)7415.864.902 nweurope@prosoft-technology.com Language spoken: English</p>
<p><b>Australasia (Australia, New Zealand)</b> Phone: +60.3.7941.2888 pacific@prosoft-technology.com Language spoken: English</p>	<p><b>Central &amp; Eastern Europe, Finland</b> Phone: +48.22.250.2546 centraleurope@prosoft-technology.com Languages spoken: Polish, English</p>
<p><b>Southeast Asia (Singapore, Indonesia, Philippines)</b> Phone: +60.3.7941.2888 seasia@prosoft-technology.com Languages spoken: English, Bahasa, Tamil</p>	<p><b>Russia &amp; CIS</b> Phone: +7.499.704.53.46 russia@prosoft-technology.com Language spoken: Russian, English</p>
<p><b>Northeast &amp; Southeast Asia (Japan, Taiwan, Thailand, Vietnam, Malaysia)</b> Phone: +60.3.7941.2888 neasia@prosoft-technology.com Languages spoken: English, Chinese, Japanese</p>	<p><b>Austria, Germany, Switzerland</b> Phone: +49.(0)1511.465.4200 germany@prosoft-technology.com Language spoken: German, English</p>
<p><b>Korea</b> Phone: +60.3.7941.2888 korea@prosoft-technology.com Languages spoken: English, Korean</p>	<p><b>BeNeLux, France, North Africa</b> Phone: +33(0)5.34.36.87.20 france@prosoft-technology.com Languages spoken: French, English</p>
	<p><b>Mediterranean Countries</b> Phone: +39.342.8651.595 italy@prosoft-technology.com Languages spoken: Italian, English, Spanish</p>

<b>Latin and South America</b>	<b>North America</b>
<p><b>Brazil, Argentina, Uruguay</b> Phone: +55.11.5084.5178 brasil@prosoft-technology.com Languages spoken: Portuguese, Spanish, English REGIONAL TECH SUPPORT support.la@prosoft-technology.com</p> <p><b>Mexico</b> Phone: +52.222.264.1814 mexico@prosoft-technology.com Languages spoken: Spanish, English REGIONAL TECH SUPPORT support.la@prosoft-technology.com</p> <p><b>Andean Countries, Central America, Caribbean, Chile, Bolivia, Paraguay</b> Phone: +507.6427.48.38 andean@prosoft-technology.com Languages spoken: Spanish, English REGIONAL TECH SUPPORT support.la@prosoft-technology.com</p>	<p>Regional Office Phone: +1.661.716.5100 info@prosoft-technology.com Languages spoken: English, Spanish REGIONAL TECH SUPPORT support@prosoft-technology.com</p>

## 2.2 Warranty Information

For complete details regarding ProSoft Technology's TERMS & CONDITIONS OF SALE, WARRANTY, SUPPORT, SERVICE AND RETURN MATERIAL AUTHORIZATION INSTRUCTIONS please see the documents at: [www.prosoft-technology.com/legal](http://www.prosoft-technology.com/legal)

Documentation is subject to change without notice.